

Todd's Automotive Services Ltd.
 5212 51 Street
 Lloydminster AB T9V 0P4
 587-605-1311
 tostenw@telus.net
 Business Number 780991873RT0001



INVOICE

BILL TO

Don Parsons
 [REDACTED]

INVOICE # 7059

DATE 01/17/2023

TERMS Due on receipt

YEAR/MAKE/MODEL:
 2007 FORD F150

MILEAGE:
 121,576

VIN:
 1FTPX14VX7FB77460

ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
MECHANICAL INSPECTION	COMPLETE STEERING, BRAKES, SUSPENSION, ENGINE COMPARTMENT AND UNDERCARRIAGE INSPECTION	1	89.00	89.00
Labour	REPLACED RIGHT REAR SHOCK ASSEMBLY (BROKEN)	0.50	89.00	44.50
Parts	SHOCK ABSORBER	1	130.03	130.03
Labour	CUSTOMER COMPLAINT OF VEHICLE HAS LOW POWER WHEN HOT. SCANNED AND FOUND CODE P0420 FOR LOW CATALYST EFFICIENCY. CHECKED AND FOUND RIGHT CONVERTER PLUGGED AND LEFT CONVERTER PARTIALLY PLUGGED. REPLACED BOTH CATAYLIC CONVERTERS. ALSO REPLACED ALL FOUR OXYGEN SENSORS. FOUND OXYGEN SENSORS SLUGGLISH.	2.80	89.00	249.20
Parts	CONVERTER	1	916.10	916.10
Parts	CONVERTER	1	933.41	933.41
Parts	OYGEN SENSOR	4	102.27	409.08
Shop Supplies	SHOP SUPPLIES	1	50.00	50.00

We accept payment by debit, credit, cash and e-transfer.

RETORQUE LUG NUTS AFTER 100 KM.

RANGE DETAILS FOR REMOTE STARTERS:

Range based on unobstructed line-of-site testing under ideal conditions. Actual range will vary due to local conditions including, but not limited to, environment, terrain, physical obstructions, vehicle location and orientation, interference and other possible impediments.

THANK YOU FOR YOUR BUSINESS AND HAVE A GREAT DAY!

SUBTOTAL	2,821.32
GST @ 5%	141.07
TOTAL	2,962.39
BALANCE DUE	\$2,962.39

TERMS & CONDITIONS:

Customer authorizes to the work to be done and the materials to be supplied and installed. Customer authorizes work to be subcontracted as needed. Customer authorizes vehicle can be driven for purpose of repairs and inspection. Payment is due in full prior to releasing vehicle.

Todd's Automotive Services is not responsible for any vehicle theft or vandalism.

st
e-transfer