Rocky Mountain Equipment Canada Ltd. o/a Rocky Mountain Equipment

KEN BRUCE	C -	Ken Bruce	
KEN BRUCE			
KEN BRUCE			
KEN BRUCE			
	KEN	BRUCE	

	JOE		
4149 39	Stree	at .	
Camros	e, AB	T4V 3X8	
Tel:	(78	80) 672-9138	3
Fax:	(78	80) 672-4582	2

Fax: (780) 672-4582 Toll Free: 1-855-763-1427

Branch	**************************************	And the second s	A CAR AND A DESCRIPTION OF A Residence of the second secon	
CAMROSE Date	Time		Page	
01/28/20	09:4	3:05 (0)	01	
Account No.	Phone No.		Reference No.	
KENBR007	7803842137		W16991	
Ship Via		Purchase Order		
		G.S.T. No.		
		825 724 032 RT0001		
Credit Card No.		Sa	Salesperson	
	s <u>a</u> x		682	

Description of Work and Parts

STK#/FLEET#

138567

CCMBINE CR960

HRS PIN/EIN

10/21/19 10/22/19

2751 HAJ101145

2043

WARRANTY DATE

HRS

Fold ----

SEGMENT# 1 S 02315 NA

Shoe noisy during operation

CORRECTION:

Brought unit up to the shop. Got a 2nd person and engaged thresher. Inspected for where the noise was coming from. Went under the unit and found a crack on the leveling frame in front of the fan housing. Dropped pick-up header of along north fence and brought unit into the shop. Made parts and labor quote. Customer came in and we discussed the repair, he gave the go ahead to repair and order the parts. Removed chopper shields, brackets and removed chopper housing from unit. Removed top sieve, bottom sieve and pre-sieve. Disassembled fan drive sheave and removed fan belt. Found wear on the outer pulley, quoted to repair at machine shop. Removed fan and housing from unit. Disconnected grain pan from upper shoe frame and supported pan out of the way. Removed LH and RH eccentric arms. RH bearing was loose in the arm. Disconnected electrical, removed upper and lower shoe frames. Set them on a pallet and moved them outside. Split clean grain elevator chain open. Removed auger bearings and moved the auger to the left in the trough. Removed trough extension shields to elevator. Separated tailings auger housings from auger trough. Supported LH shield and disassembled LH step. Removed auger trough from unit. Supported leveling frame and removed front pin and rear bearing. Lowered frame down and pulled it out. New frame took a while to get here. Once new frame was here, inspected and made sure it was right. Removed eccentric shaft from the old frame and

CONTINUED ON PAGE 02

Il hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.	I hereby acknowledge my indebtedness in the amount of \$ amount owing or balance owing as shown hereon.	being the total
(signature) (date)	(signature)	(date)