Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

C - Don Sware 780-974-0461 Ship to:

Invoice to:

DON SWARE 52429 RGE RD 183

BEAVER COUNTY AB TOB 4J5

CAMROSE

4149 39 Street

Camrose, AB T4V 3X8

(780) 672-9136

Fax (780) 672-4582 Toll Free: 1-855-763-1427

Branch		**************************************		- I grant you go
CAMROSE				
Date	Time			Page
09/28/21			0)	01
Account No.	Phone N	0.	19920	Reference No.
SWARE005	780	6623080		W21843
Ship Via		Purchase	Order	
		G.S.T. No.		The state of the s
		79759	466	0 RT0001
Credit Card No.			Sale	sperson
			6	82

## **Description of Work and Parts**

STK#/FLEET#

117859

Combine CR9070 HRS PIN/EIN

3105 HAJ110196

09/08/21 09/08/21

2200

WARRANTY DATE

HRS

# 11,105.21 G59 528.83 G59

INVOICE

- \*\* Ask us about our Red Seal Inspection Program great savings,
- \*\* peak performance, maximum uptime guaranteed. Book your inspection now!

SEGMENT# 1 C 05192 NA

Repair cracked shoe frame

COMPLAINT:

Excessive noise from shoe.

CAUSE:

Failed lower shoe frame

## CORRECTION:

- -Removed header from combine.
- -Removed spreader board, spreader and chopper housing.
- -Removed straw doors.
- -Disconnected fan motor and lowered fan housing to the ground.
- -Removed pre-sieve.
- -Disconnected upper shoe arms and removed upper shoe.
- -Disconnected lower shoe arms and removed lower shoe.
- -Removed all parts of lower shoe and installed on new lower shoe.
- -Installed shoe and connected arms.
- -Installed upper shoe, set position and installed all bushing arms.
- -Installed upper and lower sieves and calibrated.
- -Installed pre-sieve.
- -Tried to install rear access door but the new shoe has different mounting holes. Had to reorder door.
- -Installed straw doors.
- -Installed chopper housing, spread board and shield.

CONTINUED ON PAGE 02

It hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or defivery at my risk. I agree to pay cash or delivery of machine or on terms satisfactory with you and until ped in full, an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional	
(signature) (date)	(Signature) (date)

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

C - Don Sware 780-974-0461 Ship to: invoice to:

Branch	THE PERSON NAMED IN COLUMN NAM	A STATE OF THE STA			20000000
CAMROSE					
Date	Time				Page
09/28/21	16:	18:09 (	0)		02
Account No.	Phone N	0.		Refe	rence No.
SWARE005	780	6623080		W21	843
Ship Via		Purchase	Order		
	WALLES TO SERVICE THE SERVICE	G.S.T. No.	- Anna Parket State Stat		**************************************
		79759	466	0 RT	0001
Credit Card No.			Sale	sperso	on
			6	82	

HRS

Fold -

(780) 672-9136

(780) 672-4582

Toll Free: 1-855-763-1427

WARRANTY DATE

Fax:

## **Description of Work and Parts**

STK#/FLEET#

117859

(signature)

Combine

DON SWARE

52429 RGE RD 183

BEAVER COUNTY AB TOB 4J5

CR9070

HRS PIN/EIN 3105

HAJ110196

2200

-Installed belts.

-Ran combine and checked operation.-Good. Sept 10/21

Installed the LH bottom guard by the fan, had a hard time getting the hardware into place properly. Had to open up the returns and get assistance to reach under and install the bolts. Installed the guard over the fan. Tightened all hardware. Installed the hinges for the rear door above the spreaders hand tight. Installed the door and tightened all hardware once it was lined up nicely. Riveted on the rubber mat. Installed the chopper belt cover. Removed the air fitting we installed for the air riveter and reinstalled Grovers air fitting. Cleaned up all tools and garbage. Ran unit again and made sure all was good, drove it close to the gate very slowly to prevent it from getting super muddy.

Sept 11/21			
FREIGHT	FREIGHT	1 105.55	305 55
120041	BOLT, CARRIAGE	1 3.53	105.55
140045	LOCKWASHER	1 .73	3.53
210049	BALL BEARING	1 75.69	.73
322356	WASHER, LOCK	4 1.86	75.69 7.44
353308	NUT, LOCK, M6	1 .41	.41
434817	ROLLER	2 46.08	92.16
47636248	SHOE, SHAK	1 N 4243.60	4243.60
84390706	COVER	1 N 752.60	752.60
84446204	RIVET	30 0 1.16	34.80
84457842	PLATE, WEAR	1 74.67	74.67
86507486	BOLT, SSQ	2 3.14	6.28
86529373	HINGE	3 11.44	34.32
		CONTINUED ON PAGE 03	

hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and unit paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that he conserved mechanic's lien is acknowledged on above machine to secure the amount	
of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theit or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.	

I hereby acknowledge my indebtedness in the amount of \$ amount owing or balance owing as shown hereon.	being the	total
---	-----------	-------

(Signature)



Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

C - Don Sware 780-974-0461 Ship to: Invoice to: DON SWARE 52429 RGE RD 183 BEAVER COUNTY AB TOB 4J5 CAMROSE 4149 39 Street

Camrose, AB T4V 3X8

Tel: (780) 672-9136 (780) 672-4582 Toll Free: 1-855-763-1427

NVO	IC	E
-----	----	---

Branch		CONTRACTOR OF THE PARTY OF THE	w-with-coordina	Vennere eskikikko vii	Contribution without a constitution of
CAMROSE					
Date	Time				Page
09/28/21	16:	18:09 (	0)		03
Account No.	Phone N	lo.		Refe	rence No.
SWARE005	780	6623080		W21	843
Ship Via	The state of the s	Purchase	Order		
		G.S.T. No.			
		79759	466	0 RT	0001
Credit Card No.			Sales	sperso	n n
			6	82	

## **Description of Work and Parts**

STK#/FLEET#		HRS	PIN/EIN	WA	RRA	NTY DATE	HRS	<b>₹</b>
117859	Combine	3105	HAJ110196					
	CR9070	2200						
86625263		WASHER		1		.49		.49
87000280		STRIP		1		67.24		67.24
87105832		SEAL		1	N	57.41		57.41
87370007		PLATE		1	N	33.06		33.06
87370009		PLATE		1	N	37.38		37.38
87471830		SCREW, I	HEX	1	N	6.04		6.04
87585352		CANVAS		2		112.46		224.92
87613322		RIVET,	POP	4		.56		2.24
87711044		BLOCK		1 1	N	8.52		8.52
						PARTS		5869.08
						LABOR		4260.00
13500028				SEGMEN	T.	TOTAL==>		10129.08

\*\*\*\*\* WORK ORDER TOTALS \*\*\*\*\* **PARTS** 5869.08 LABOR 4260.00

11105.21

DISPOSAL FEE 85.20 SHOP SUPPLIES 362.10 SUB TOTAL ==> 10576.38 GST 797594660 528.83

VISA

028360 NP



	I hereby acknowledge my indebtedness in the amount of \$amount owing or balance owing as shown hereon.	being the total
signature) (date)	(signature)	(date)