

Ship to:	C - Don Sware
Invoice to:	DON SWARE 52429 RGE RD 183 BEAVER COUNTY AB TOB 4J5

Branch					
CAMROSE					
Date	Time				Page
01/29/20		35:53 (0)		01
Account No.	Phone N	0.		Refe	rence No.
SWARE005	780	5623080		W17	448
Ship Via		Purchase	Order		
		G.S.T. No.			
_		825 7	24 03	2 RT	0001
Credit Card No.		Sales	sperso	n	
			6	82	

Description of Work and Parts

Tel:

Toll Free: 1-855-763-1427

STK#/FLEET	°#
------------	----

136730

Combine CR9070

HRS PIN/EIN 2811 HAJ111372

2026

SEGMENT# 1 5 00770 NA

01/21/20 01/23/20

Perform RedSeal inspection

CORRECTION:

- -run unit up to verify operation
- -perform all running checks
- -remove header from combine
- move unit into shop
- -perform Red Seal inspection
- make list of repairs required, labor and parts quote
- -go through inspection with customer
- ordered parts for repairs that are approved by customer

13300028

SEGMENT TOTAL ==>

WARRANTY DATE

HRS

LABOR

1085.07

				WORK	ORDER	TOTALS	****
		L	ABOR			10	85.07
	DIS	POSAL	FEE				21.70
	SHOP	SUPPI	LIES				92.23
	SUB	TOTAL	\==>			11	99.00
		825724					59.95
MATO	CASH/I	DEBIT/	CHK			12	58.95

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is admonifiedged on above machine to secure the amount of repars hereto. It is understood that the company assumes no responsibility for loss or damage by theft or tire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.	1
(signature) (date)	(signature) (date)

C - Don Sware DON SWARE		DON SWARE
		52429 RGE RD 183
	52429 RGE RD 183	

4149393	Street
Camrose	, AB T4V 3X8
Tel:	(780) 672-9136
Fax:	(780) 672-4582
Toll Free:	1-855-763-1427

CAMROSE

Branch					
CAMROSE					
Date	Time				Page
01/29/20		29:13	(0)		01
Account No.	Phone N	0.		Refe	rence No.
SWARE005	7806	6623080		W17	494
Ship Via		Purchase	Order		
		G.S.T. No			
		825 7	24 03	32 R1	T0001
Credit Card No.			Sales	sperso	n
			В	44	

3.00

3.00

Description of Work and Parts

SEGMENT# 1 5 00770 NA

01/24/20 01/24/20

76C Pickup header

01/24/20 01/24/20

CORRECTION:

- remove auger drive chain
- remove pto shaft and shield
- remove mount hardware from pto jack shaft support
- take shaft and support into shop
- dis assembled shaft and found that outer bearing had spun on shaft
- assemble new shaft into new bearings
- installed 2 new bearing flanges and reused 2
- installed bolts into bearing flanges and aligned
- secure bearing flanges and lock collars
- install spacer and shims behind sprocket
- install sprocket, nut and new cotter pin
- install support back onto header
- install pto shaft shield
- install pto shaft
- re-install auger drive chain and set Chain tension
- install side panel

ADDITIONAL DESCRIPTION:

- jackshaft, bearings, flanges and lock collars (3)
- pick up belt drive motor leaking, quote seal kit and motor(OMIT)
- replace auger drive chain (OMIT)

FREIGHT	Freight	3	20.00	60.00
370006	RING, SNAP	1	8.51	8.51
370007	RING, SNAP	1	10.25	10.25
374129A1	BEARING	2	88.56	177.12
		CONTT	INTIED ON DACE 02	

	I hereby admowledge my indebtedness in the amount of \$ amount owing or balance owing as shown hereon.	being the total
(signature) (date)	(signature)	(date)

C - Don Sware Ship to: Invoice to: DON SWARE 52429 RGE RD 183 BEAVER COUNTY AB TOB 4J5

CAMROSE	INVOICE
4149 39 Street	IIIAOICE

4149 39 Stree Camrose, AB T4V 3X8 Tel (780) 672-9136 Fax: (780) 672-4582 Toll Free: 1-855-763-1427

Branch					
CAMROSE					
Date	Time				Page
01/29/20		29:13 (0)		02
Account No.	Phone N	0.		Refe	rence No.
SWARE005	7806	6623080		W17	494
Ship Via		Purchase	Order		
					1
		G.S.T. No.			
		825 7	24 03	2 RT	0001
Credit Card No.	Salesperson		n		
			Е	44	

Description of Work and Parts

STK#/FLEET# 136730	Combine CR9070	s	HRS X 2026	PIN/EIN HAJ111372	WARE	ANTY DATE	HRS	Fold
374131A1 450716 84120742 84441185 86989897 87306803 87673358 9514334			HOUSING BEARING WASHER, BEARING HEAD BEARING, SHAFT ROD	AS	1 1 N 1 S 1 S 1 M 1 N	20.25 52.85 10.34 45.24 405.00 30.31 423.50 24.30 PARTS		20.25 52.85 10.34 45.24 405.00 30.31 423.50 24.30
13300028					SEGMENT	LABOR TOTAL==>		438.40 1706.07

SEGMENT# 2 5 00770 NA

01/24/20 01/24/20

Feeder House

CORRECTION:

2.00

2.00

- remove front tin shields to gain access to feeder chain
- loosen feeder chain tension and split feeder chain
- roll new feeder chain out on floor
- attach new chain to old chain and roll new chain into feeder house
- found that the front drum was installed backwards and was interfering with the center connector link
- remove from feeder house
- when drum was on the floor noticed that the shaft in to front drum was bent and is causing the bearings to pivot in there housings
- phoned customer to let him know, got the go ahead to fix
- dis assembled front drum
- install new shaft and bearings

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may on above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on other yor of machine or or satisfactory with you and until paid in full, an express mechanics lien is activowindged on above machine to secure the am of repairs therefor. It is understood that the company assumes no responsibility for loss or damage by their or fire to machin placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.	mis hereby acknowledge my indebtedpass in the amount of 6
(signature) (date)	(signature) (date)

		of a meanly meantaint Equipment
Ship to:	C - Don Sware	
Invoice to:	DON SWARE 52429 RGE RD 183 BEAVER COUNTY AB	T0B 4J5

Branch		***************************************			
CAMROSE					
Date	Time				Page
01/29/20		29:13 (0)		03
Account No.	Phone N	0.		Refe	rence No.
SWARE005	780	6623080		W17	494
Ship Via		Purchase	Order	,	
	,				
		G.S.T. No.			
		825 7	24 03	32 R1	T0001
Credit Card No.			Sale	sperso	on
			_		- 1

CAMROSE 4149 39 Street

(780) 672-9136 (780) 672-4582 Toll Free: 1-855-763-1427

		Description of W	ork and	Parts		
STK#/FLEE	r#	HRS PIN/EIN	Wat	RRANTY DATE	IIDo	
136730	Combine	X HAJ111372	WAL	CRANTI DATE	HRS	Fold -
	CR9070	S 2026				
- instal	led new lock coll					
	alled drum arms					
- found i	rh side spring gu	age is broke when is was	dis			
assembled	1		420			
- install	led 1 new guage o	on rh side				
	drum back into					
 install 	all mounting ha	rdware				
- connect	new feeder chai	n				
- tension	feeder chain to	spring guage				
ADDITIONA	L DESCRIPTION:					
- new fee	der chain					
7120024		SCREW	1	2.20		2.20
84075251		INDICATOR	1	12.90		12.90
84186415		SHAFT	1	136.64		136.64
86629542		NUT	1	.49		.49
87297793		PACKAGE	2	162.00		324.00
87372057		CR970 FDR CHAIN	1	2977.73		2977.73
				PARTS		3453.96
*				LABOR		724.73
13300028			SEGMEN	r TOTAL==>		4178.69
EGMENT# 3	5 03302 NA	01/24/20 01/24/20				
Engine				10.50	10.50	

s

remove fan belts- remove bolts securing fan brace- remove fan brace- remove pulley- remove fan shaft- install new fan shaft and bearings, install pulley- remove tensioner replace bushings and bearings in arm- install fan braceinstall belts- run up and check operation- good. blew out cab air filters- installed new pto fill cap-

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's ten is admonétiqued in above machine to secure the amount of repairs theretor, it is understood that the company assumes no responsibility for loss or damage by theft or tire to machine placed with them for storage, sale, repair or whate being tested. Estimates are for labour only, materials additional.	homby advantados my indobb doses in the consent of the	being the total
(signature) (date)	(signature)	(date)

C - Don Sware Ship to: ġ DON SWARE 52429 RGE RD 183 nvoice BEAVER COUNTY AB TOB 4J5

CAMROSE 4149 39 Street Camrose, AB T4V 3X8 (780) 672-9136 Fax:

(780) 672-4582 Toll Free: 1-855-763-1427

Branch				
CAMROSE Date	Time			Page
01/29/20 Account No.	13:3 Phone N	29:13 (0)	04 Reference No.
SWARE005	780	623080 Purchase		W17494
Ship Via				
		G.S.T. No. 825 7		32 RT0001
Credit Card No.			Sale	sperson
			E	44

Description of Work and Parts

WARRANTY DATE HRS HRS PIN/EIN STK#/FLEET# х нај111372 Combine 136730 2026 CR9070

replaced engine oil and filter- drain coolant down- install new level sensor- reinstall coolant.

ADDITIONAL DESCRIPTION:

- engine oil and filter (1.5)
- outer engine filter (OMIT)
- engine gearbox filler cap broken (0.5)
- replace engine fan belt tensioner arm bushings and

bearing for idler pulley (2)

- -engine fan bearings and shaft (3)
- Blow out cab air filter

86570754 87377459	CAP SENSOR	1	45.62 114.24 PARTS LABOR	114.24 519.33 1327.53 1846.86
382974 73341701 73341702	15/40 CJ4EN 2.5 15/40CJ4ENG 5G	1	63.13 115.00	63.13 115.00 45.62
LF3977 OIL1	ENVIRO OIL LTR BUSHING	29 2	.10 8.10	2.90 16.20
 coolant level sensor change FIL2 	(3) ENVIR FILT>8" FILTER, ENGINE	2 2	1.00 80.12	2.00 160.24

SEGMENT# 4 5 00770 NA

01/24/20 01/24/20

Electrical

CORRECTION:

- remove inner dome light assembly
- swap wiring to new light asssmbly
- verify proper operation
- remove and replace sieve light bulb

CONTINUED ON PAGE 05

1.00

1.00

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my tisk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's ten is advisorabled on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theti or fire to mechine placed with them for storage, sale, repair or white being tested. Estimates are for labour only, materials additional.	It has be not not be a second of the contract of S	being the total
(signature) (date)	(signature)	(date)

4149 39 Street Camrose, AB T4V 3X8 (780) 672-9136 (780) 672-4582 Toll Free: 1-855-763-1427

CAMROSE

ı			10		
ı	N	V	0	ı	

	record in Contrast Equipment Canada Ltd. o/a Rocky Mountain Equipment
Ship to:	C - Don Sware
Invoice to:	DON SWARE 52429 RGE RD 183 BEAVER COUNTY AB TOB 4J5

Branch					
CAMROSE					
Date	Time				Page
01/29/20	13:2	29:13 (0)		05
Account No.	Phone N	0.		Refe	rence No.
SWARE005	7806	623080		W17	494
Ship Via		Purchase	Order		
		G.S.T. No.			
		825 72	24 03	32 R	T0001
Credit Card No.			Sale	sperso	on
			Е	44	

Description of Work and Parts

STK#/FLEET# 136730 Combine CR9070	HRS PIN/EIN X HAJ111372 S 2026	WARRANTY DATE	HRS	Fold
- verify proper operation ADDITIONAL DESCRIPTION: - replace sieve light bulb - LH work light bulb under - replace inner dome light FREIGHT 82022833	roof cap (OMIT)	1 17.00 1 N 78.78		17.00
13300028	BULB, HALOGEN	1 18.25 PARTS LABOR SEGMENT TOTAL==>		78.78 18.25 114.03 98.64 212.67
SEGMENT# 5 5 00770 NA Threshing CORRECTION:	01/24/20 01/24/20	10.00	10.00	

- remove main drive belt off engine gearbox
- remove unload auger drive belt
- remove pulley from tension arm for main drive belt
- remove roll pin, tension rod and arm assembly from pivot pin
- found pin to have excessive wear and the bushing in the
- remove bushings from arm and install new ones
- remove securing bolts from pivot pin and use air hammer to drive pin out of housing
- install new pin and secure in position
- install arm and new tension rod onto pin and secure in place with roll pin
- install pulley on tensioner arm
- install previously removed belts and tighten up to spring

	I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operat above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on larm satisfactory with you and until paid in full, an express mechanic's lien is admovideded on above machine to secure the amour of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.	. 1
-	(signature) (date)	(signature) (date)



_		ourida Ltd. 0/ a Kocky Mountain Equipment
	C - Don Sware	
,	DON SWARE 52429 RGE RD 183 BEAVER COUNTY AB	TOB 4J5

OVINIVOSE
4149 39 Street
Camrose, AB T4V 3X8
Tel: (780) 672-9136
Fax: (780) 672-4582
Toll Free: 1,855,762,1407

CAMPOSE

Toll Free: 1-855-763-14	27				
Branch					
CAMROSE Date	Time				
01/29/20		29:13 ((0)		Page
Account No.	Phone N	0.	0)	Refe	06 rence No.
SWARE005 Ship Via	780	6623080		W17	494
Simp via		Purchase	Order	,	
		G.S.T. No.			
Credit Card No.		825 7	24 03	32 RT	0001
Oredit Card No.			Sales	sperso	n
			E	44	

Description of Work and Parts

STK#/FLEET#	HRS PIN/EIN		
136730 Combine	X HAJ11137	WARRANTY DATE	HRS Fold -
CR9070	S 2026	2	Policy
gauge	2020		
 remove mount bolts fr 	Om pre sieve		
remove pre sieve from	combine		
 found there was wear 	on the pivot rod for the		
and was causi	ig blav	pre sieve	
 used welder and built 	it up		
 installed and remove r 	ore sieve a few times to	hank 61:	
mage			
 also made adjustments 	on linkages on pre sieve		
 install pre sieve and 	secure in place with har	dua	
ADDITIONAL DESCRIPTION:		dware	
- LH rotor gearbox seal	weeping (OMIT)		
 LH main drive bushing 	and pin/shaft that arm m	Ounts to	
(4)		cuits to	
 Check pre-sieve linkag 	e		
FREIGHT	Freight	1 20.00	
395589	SLEEVE	20.00	20.00
412126	NUT, LOCK M12	27.20	34.52
412660	PIN, ROLL	- 2.33	2.35
84057940	SHAFT	1 N 3.54 1 N 183.60	3.54
84072232	ROD	203.00	183.60
916107	WASHER	1 N 62.16 1 8.22	62.16
		- 0.22	8.22
122444		PARTS	314.39
13300028		LABOR SEGMENT TOTAL==>	846.66
		TOTAL==>	1161.05

SEGMENT# 6 5 03302 NA

01/24/20 01/28/20

Shoe

CORRECTION:

1.50

1.50

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. Lagree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's ten is admovifieded on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by their or fire to machine placed with them for storage, sale, repair or white being tested. Estimates are for labour only, materials additional.	I hereby acknowledge my indebtedness in the amount of \$
(signature) (date)	(signature) (date)

Ship to:	C - Don Sware	
Invoice to:	DON SWARE 52429 RGE RD 183 BEAVER COUNTY AB	T0B 4J5

0					
Branch					
CAMROSE					
Date	Time				Page
					90
01/29/20	13:	29:13 (0)		07
Account No.	Phone N	0	~	Refe	rence No.
		• .		1	101100 140.
SWARE005	780	5623080		W17	494
Ship Via		Purchase			171
		1 di di di di	Oraci		
					- 1
		G.S.T. No.			
					- 1
		825 7	24 03	32 R	Γ0001
Credit Card No.			Sale	sperso	on
				•	
			E	44	

Description of Work and Parts

Fax:

(780) 672-4582 Toll Free: 1-855-763-1427

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS 136730 Combine X HAJ111372 CR9070 2026

cut metal to fit - tack in place- silicone gaps- paint ADDITIONAL DESCRIPTION:

- weld steel plates to fill in gaps on shoe seal

LABOR 183.58 13300028 SEGMENT TOTAL ==> 183.58

SEGMENT# 7 5 00770 NA

01/24/20 01/24/20

5.00

CONTINUED ON PAGE 08

5.00

Fold - -

misc

- remove mount hardware from psd drive motor

- slide motor back and remove worn out rubber cushion in love joy coupler
- install new cushion
- install drive motor back into position and install mount
- drain hydraulic oil into clean pails
- remove suction hose from hydraulic tank to tee fitting
- remove suction hose from tee fitting to pfc hydraulic pump
- get new hoses from schnell and Barrie
- install both new suction hose into position
- secure with new clamps on tee fitting and hydraulic tank
- fill hydraulic tank with oil that was previously removed
- wash area after repairs were complete to clean up spilled oi1
- start unit , shut off and verify levels were correct ADDITIONAL DESCRIPTION:
- replace rubber pad on psd belt drive motor (1)
- hydraulic tee above chopper belt leaking (4)

FREIGHT

Freight

I hereby authorize the above work to be done along with the use of necessary materials. You and your employs above machine for purposes of testing, inspection or delivery at mis it. I agree to pay cash on delivery of mic satisfactory with you and until paid in full, an express mechanic's lien is admowledged on above machine to se of repairs therefor. It is understood that the company assumes no responsibility for loss or damage by their of placed with them for storage, sale, repair or white being tested. Estmattes are for labour only, materials addition	e or on terms e the amount I hereby acknowledge my indebtedness in the amount of \$	being the total
(signature) (date)	(signature)	(date)

20.00-



DON SWARE 52429 RGE RD 183 BEAVER COUNTY AB TOB 4J5	-		,
		C - Don Sware	
	3		
DON SWARE 52429 RGE RD 183 BEAVER COUNTY AB TOB 4J5	ם ר		
52429 RGE RD 183 BEAVER COUNTY AB TOB 4J5	ii [DOM CHARD	
BEAVER COUNTY AB TOB 4J5	5		
BEAVER COUNTY AB TOB 4J5	3		
	5	BEAVER COUNTY AB	T0B 4J5
	- L		

Camrose,	AB T4V 3X8
Tel:	(780) 672-9136
Fax:	(780) 672-4582
Toll Free:	1-855-763-1427
Branch	

CAMROSE 4149 39 Street

Branch					
CAMROSE					
Date	Time				Page
01/29/20	13:2	29:13 (0)		08
Account No.	Phone No.		Reference No.		
SWARE005	7806623080		W17494		
Ship Via	Purchase Order				
		G.S.T. No.			
		825 724 032 RT0001			T0001
Credit Card No.		Salesperson		on	
			E	44	

Description of Work and Parts

STK#/FLEET# 136730	Combine		HRS PIN/EIN X HAJ111372		ANTY DATE	HRS	Fold
	CR9070	S	2026				
OSD-150S-2	0		Hose	6	10.75		64.50
40-43			CLAMP	3	5.30		15.90
87031918			SPIDER	1 S	70.85		70.85
					PARTS		131.25
					LABOR		202.76
13300028				SEGMENT	TOTAL==>		334.01
SEGMENT# 8	5 00770 NA		01/24/20 01/28/20				
Post Run u	p and calibr	ation			3.00	3.00	
CORRECTION	1						
- move uni	t outside						
- attach p	ick-up heade	er					
	-		rforming repairs				
	roper operat						
	r leaks no 1						
	yard for cus						
CUSTDIS	, a.z.a z.z.a c.z.a		CUSTOMER DISC	1-	580.06		580.06-
COSIDIS			332131	_	PARTS		580.06-
					LABOR		337.02
13300028				SEGMENT	TOTAL==>		243.04-

PARTS 5220.57
LABOR 4159.32
DISPOSAL FEE 83.18
SHOP SUPPLIES 353.54
DISCOUNT 415.95SUB TOTAL==> 9400.66

It hereby authorize the above work to be done along with the use of necessary materials. You and your employees many operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until poid in full, an express mechanic's lien is admonified on above machine to secure the amount of repairs therefor, it is understood that the company assumes no responsibility for loss or damage by their or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.	hereby acknowledge my indebtedness in the amount of \$ being the total amount owing or balance owing as shown hereon.		
(date)	(signature)	(date)	



Rocky Mountain Equipment Canada Ltd. o/a Rocky Mountain Equipment C - Don Sware Ship to: Invoice to: DON SWARE 52429 RGE RD 183 BEAVER COUNTY AB TOB 4J5

CAMROSE	INVOICE
4149 39 Street	INVOICE
Camrose, AB T4V 3X8	

4149 39 Camrose Tel: (780) 672-9136 Fax: (780) 672-4582 Toll Free: 1-855-763-1427

Branch				
CAMROSE				
Date	Time			Page
01/29/20 Account No.	13:	29:13 (09
	Phone N	0.	Re	eference No.
SWARE005	780	6623080	W1	7494
Ship Via		Purchase	Order	, , ,
		G.S.T. No.		
		825 724 032 RT0001		
Credit Card No.			Salesper	rson
			R44	

Description of Work and Parts

STK#/FLEET#

136730

Combine

HRS PIN/EIN X HAJ111372

WARRANTY DATE

HRS

CR9070 2026

GST 825724032

470.08 9870.74

TOTAL CASH/DEBIT/CHK

870.74 11/29.69 Total

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, on express mechanic's lien is admoveleded on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale repair or while being tested. Estimates are for labour only, materials additional.	North administration in the text of the control of	
(signature) (date)	(signature) (date)	-