Multi-Point Inspection Checklist Per Manufacturer's Recommendation

Customer Name:		Year/Model: F- 150 Date: TAV, 17	7/2
RO/Tag:	Mileage: 121,576	1FTPX14VX7FB77460	
OKAY AT THIS TIME	MAY REQUIRE FO	UTURE ATTENTION REQUIRES PROMPT ATTENTION	
Check Fluid Levels and Fill		Officer venerally experience	clined
OK FILL OK FILL  OK FILL  OK FILL  OK FILL	OK FILL  Reservoir OPower Steering	Operation of horn, interior lights, exterior lamps, turn signals, hazard and brake lamps	0
Transmission Window Washer Coolant Recovery Reservoir		Radiator, heater, and air-conditioning hoses for leaks and damage	0
Recommended Scheduled Maintenance Services		Windshield for cracks, chips and pitting	
Oil Change	O Fuel Filter	Windshield washer spray, wiper operation and wiper blades	
Oil Filter	Cabin Air Filter	0/0 0	
Engine Air Filter	O Spark Plugs	Accessory drive belt(s)	
C Engine Coolant C Tire Rotation		Brake system (including lines, hoses, and parking Brake) and wheel end for end-play and bearing noise	
Transmission Fluid	O Seat Filter	Clutch operation (if equipped)	0
Transmission Filter	Accessory Drive Belt(s)	Constant velocity (CV) drive axle boots (if equipped)	0
Comments:		Drive shaft, transmission, u-joint and shift linkage (if equipped) and lubricate (as needed)	0
		Engine Cooling system, hoses and clamps	0
Check E	Battery	Exhaust system (leaks, damage, loose parts)	0
State of Health	Good Bad	Oil and / or fluid leaks	0
	Battery Terminals (Clean if necessary)	Shocks/struts and other suspension components for leaks and/or damage	0
0%	100% Declined Battery	Steering and steering linkages	0
Check Brakes Measure Front / Rear Brakes Linings		State Inspection Due (IF APPLICABLE) / / DAY / YEAR	
LF RF		Comments:	
Ø 31 T			
		Check Tires	
		LF TREAD DEPTH	RF
		7/32" or Greater 7/32" or Greater	~
		4/32" to 6/32" 4/32" or less 3/32" or less	_
		7/32" or Greater 7/32" or Greater 4/32" to 6/32"	
LR U	RR	3/32" or less 3/32" or less	
	Declined Brake	LR	RR
Over 5 mm or 7/32" (Disc) or Over 2 mm or 3/32" (Drum)		Declined Tire	, 0
3 to 5 mm or 4/32" to 7/32" (Disc) or 1.01 to 2mm (Drum) or 2/32" to 3/32"		□ □ □ LF WEAR PATTERN / DAMAGE RF □ □	
Less than 3 mm or 4/32" (Disc) or 1 mm or 2/32" or Less (Drum)  Brake Measurements Not Taken This Service Visit		lr RR	
Brake Measurements Not 13	aken i nis Service visit	Tire Wear Indicates:  Alignment Check Needed Wheel Balance Needed	,
Comments:		Comments:	
	Tire Pressure Set to Factory Recommended PSI		
Service Advisor:	FRONT REAR		
Technician: JUA		Customer Signature:	

Reorder from A Plus Direct • 1-800-334-6329 • AP-7291