

REPAIR ORDER

BOX 35
HEISLER, ALTA. T0B 2A0
GST # R125406447 PH. 889-3982

DATE: July 200 5

CUSTOMER <i>David Giedemann</i>		PHONE ✓		FAX ✓														
ADDRESS			ORDER NO.															
JOB LOCATION <i>8570 John Deere Tractor</i>			JOB PHONE															
INSTRUCTIONS <i>Service Call - Engine Runs Poor (Missing No 2 Cyl) Disassemble Engine - Found Broken Piston No 2 Installed New Piston + Liners - Rings & Rod Bolts</i>																		
WORK DONE																		
SERVICED BY		HOURS ____ X ____	PEOPLE ____ X ____	RATE ____	<i>Thank you!</i> <table border="1"> <tr> <td>TOTAL LABOUR</td> <td><i>1050.00</i></td> </tr> <tr> <td>TOTAL PARTS</td> <td></td> </tr> <tr> <td>SUBTOTAL</td> <td></td> </tr> <tr> <td>G.S.T.</td> <td><i>73.50</i></td> </tr> <tr> <td>P.S.T.</td> <td>✓</td> </tr> <tr> <td>TOTAL</td> <td><i>1123.50</i></td> </tr> </table>		TOTAL LABOUR	<i>1050.00</i>	TOTAL PARTS		SUBTOTAL		G.S.T.	<i>73.50</i>	P.S.T.	✓	TOTAL	<i>1123.50</i>
TOTAL LABOUR	<i>1050.00</i>																	
TOTAL PARTS																		
SUBTOTAL																		
G.S.T.	<i>73.50</i>																	
P.S.T.	✓																	
TOTAL	<i>1123.50</i>																	
The above work has been completed satisfactorily and I acknowledge my indebtedness as shown on right.																		
DATE: _____		200 _____																
CUSTOMER'S SIGNATURE: _____																		